

**PRO-LAB/SSPTM INC.**  
 3300 Corporate Avenue, Bldg., 112  
 Weston, Florida 33331  
 Toll Free: 800-427-0550

**Mold Analysis Report**  
**NON-VIABLE Spore Trap M5**

**Report Number:** 012804-0188  
**Received Date:** 1/28/2004  
**Reported Date:** 1/28/2004  
**Analysis By:** SSPTM, Inc.

**Test Address:**  
 BELL- HHI SC, ,

*Alyssa Murray*

Alyssa Murray, QAQC

**Client:**  
 I.A.Q.  
 Rt 1 Box 201 A  
 Hardeeville, SC 29927

**Comments:**

**Phone:** (843) 247-9289

**Fax:**

**Email:** AIRQUALITY@HARGRAY.COM

**Your Results**

**Pro-Lab Number:** 012804-0188  
**Date Collected:** 1/24/2004  
**Collection Location:** HOUSE  
**Sample Submitted:** Micro 5  
**Volume (L):** 25  
**Chain of Custody#** 130230  
**Serial #:** 166746

Spore Identification	Results M5		Results M5	
	Raw Score	(Spores/m <sup>3</sup> )	Raw Score	(Spores/m <sup>3</sup> )
Arthrinium	2	80	0	0
Chaetomium	1	40	0	0
Cladosporium	77	3080	0	0
Curvularia	2	80	0	0
Epiccocum	1	40	0	0
Hyphae	3	120	0	0
Other Ascospores	10	400	0	0
Other Basidiospores	3	120	0	0
Penicillium/Aspergillus	34	1360	0	0
<b>Total Spores (Spores/m<sup>3</sup>):</b>		<b>5320</b>		<b>0</b>

**Analysis Date:** 1/28/2004

**AnalystID:** 11

**Analysis Date:**

**AnalystID:**

The above information was compiled by PRO-LAB/SSPTM Inc. from the EPA "A Brief Guide to Mold, Moisture, and Your Home" and the NYC Dept of Health " Guidelines on Assessment and Remediation of Fungi in Indoor Environments", at the request of and for the exclusive use of the client named on this report. This document is not a legal mandate and should be used for informational purposes only. Currently there are no Federal regulations for evaluating potential health effects of fungal contamination and remediation. This information is subject to change as more information regarding fungal contaminants becomes available. For more information: visit <http://www.epa.gov/iaq/molds/index.html> or [www.nyc.gov/html/doh/html/ei/eimold.html](http://www.nyc.gov/html/doh/html/ei/eimold.html). This document was designed to follow currently known industry guidelines for the interpretation of microbial sampling, analysis, and remediation. Since interpretation of mold analysis reports is a scientific work in progress, it may as such be changed at any time without notice. The client is solely responsible for the use and interpretation of these recommended action guidelines. PRO-LAB/SSPTM Inc. makes no express or implied warranties as to such use or interpretation. PRO-LAB/SSPTM Inc. is not able to make and does not make a determination as to the environmental soundness, safety or health of a property from only the samples sent to their laboratory for analysis. The Client is hereby notified that due to the subjective nature of fungal analysis and the mold growth process, laboratory samples can and do change over time relative to the originally sampled material. PRO-LAB/SSPTM Inc. reserves the right to properly dispose of all samples after the testing of such samples are sufficiently completed or after a 7 day period, whichever period is greater. PRO-LAB / SSPTM, Inc. participates in the AIHA EMPAT program. Lab ID #163230

**PRO-LAB/SSPTM INC.**  
 3300 Corporate Avenue, Bldg., 112  
 Weston, Florida 33331  
 Toll Free: 800-427-0550

**Mold Analysis Report**  
**NON-VIABLE Spore Trap M5**

**Report Number:** 012804-0188  
**Received Date:** 1/28/2004  
**Reported Date:** 1/28/2004  
**Analysis By:** SSPTM, Inc.

**Test Address:**

BELL- HHI SC, ,

*Alyssa Murray*

Alyssa Murray, QAQC

**Client:**

I.A.Q.  
 Rt 1 Box 201 A  
 Hardeeville, SC 29927

**Comments:**

**Phone:** (843) 247-9289

**Fax:**

**Email:** AIRQUALITY@HARGRAY.COM

**Your Results**

*The following fungal descriptions are pertinent to the samples collected. General characterization of mold is made with respect to their most common impact to human health. Many genera of molds have species with varying characteristics.*

Spore Name	Description
Arthrinium	A COSMOPOLITAN FILAMENTOUS FUNGUS OCCASIONALLY FOUND INDOORS. ISOLATED FROM PLANT DEBRIS AND SOIL. THERE ARE NO INFECTIONS SO FAR REPORTED IN HUMANS OR ANIMALS.
Chaetomium	COMMONLY FOUND ON A VARIETY OF SUBSTANCES CONTAINING CELLULOSE INCLUDING PAPER AND PLANT COMPOST. IT CAN READILY BE FOUND ON THE DAMP OR WATER DAMAGED PAPER IN SHEETROCK. SHOULD BE CONSIDERED ALLERGENIC. THE THERMOPHILIC, NEUROTROPIC NATURE OF THIS ORGANISM SUGGESTS IT IS POTENTIALLY AGGRESSIVE. NO TOXIC DISEASES HAVE BEEN DOCUMENTED TO DATE.
Cladosporium	COMMONLY FOUND ON DEAD PLANTS, WOODY PLANTS, FOOD, STRAW, SOIL, PAINT AND TEXTILES. COMMON CAUSE OF EXTRINSIC ASTHMA (IMMEDIATE-TYPE HYPERSENSITIVITY: TYPE I). ACUTE SYMPTOMS INCLUDE EDEMA AND BRONCHIOSPASMS; CHRONIC CASES MAY DEVELOP PULMONARY EMPHYSEMA. REPORTED TO BE ALLERGENIC.
Curvularia	REPORTED TO BE ALLERGENIC. IT MAY CAUSE CORNEAL INFECTIONS, MYCETOMA AND INFECTIONS IN IMMUNE COMPROMISED HOSTS.
Epiccocum	A COMMON ALLERGEN FOUND IN PLANTS, SOIL, GRAINS, TEXTILES, AND PAPER PRODUCTS. SECONDARY INVADER OF DAMAGED PLANT TISSUE. COMMON CAUSE OF TYPE I ALLERGIES (HAY FEVER, ASTHMA). NO CASES OF INFECTION HAVE BEEN REPORTED IN HUMANS OR ANIMALS.
Hyphae	PIECES OF FUNGAL ORGANISMS THAT CANNOT BE IDENTIFIED AS TO WHAT GENUS THEY ARE FROM. THEY CAN BE CONSIDERED ALLERGENIC AND ARE INDICATIVE OF ACTIVE GROWTH IN THE SAMPLING VICINITY.
Other Ascospores	ONE OF THE MAJOR CLASSES OF FUNGAL ORGANISMS. THIS CLASS CONTAINS THE "SAC FUNGI" AND YEASTS. ASCOMYCETE SPORES ARE REPORTED TO BE ALLERGENIC.
Other Basidiospores	ONE OF THE MAJOR CLASSES OF FUNGAL ORGANISMS. THIS CLASS CONTAINS THE MUSHROOMS, SHELF FUNGI, PUFFBALLS, AND A VARIETY OF OTHER FUNGI. BASIDIOMYCETE SPORES ARE REPORTED TO BE ALLERGENIC.

The above information was compiled by PRO-LAB/SSPTM Inc. from the EPA "A Brief Guide to Mold, Moisture, and Your Home" and the NYC Dept of Health " Guidelines on Assessment and Remediation of Fungi in Indoor Environments", at the request of and for the exclusive use of the client named on this report. This document is not a legal mandate and should be used for informational purposes only. Currently there are no Federal regulations for evaluating potential health effects of fungal contamination and remediation. This information is subject to change as more information regarding fungal contaminants becomes available. For more information: visit <http://www.epa.gov/iaq/molds/index.html> or [www.nyc.gov/html/doh/html/ei/eimold.html](http://www.nyc.gov/html/doh/html/ei/eimold.html). This document was designed to follow currently known industry guidelines for the interpretation of microbial sampling, analysis, and remediation. Since interpretation of mold analysis reports is a scientific work in progress, it may as such be changed at any time without notice. The client is solely responsible for the use and interpretation of these recommended action guidelines. PRO-LAB/SSPTM Inc. makes no express or implied warranties as to such use or interpretation. PRO-LAB/SSPTM Inc. is not able to make and does not make a determination as to the environmental soundness, safety or health of a property from only the samples sent to their laboratory for analysis. The Client is hereby notified that due to the subjective nature of fungal analysis and the mold growth process, laboratory samples can and do change over time relative to the originally sampled material. PRO-LAB/SSPTM Inc. reserves the right to properly dispose of all samples after the testing of such samples are sufficiently completed or after a 7 day period, whichever period is greater. PRO-LAB / SSPTM, Inc. participates in the AIHA EMPAT program. Lab ID #163230

**PRO-LAB/SSPTM INC.**

3300 Corporate Avenue, Bldg., 112

Weston, Florida 33331

Toll Free: 800-427-0550

**Test Address:**

BELL- HHI SC, ,

**Client:**

I.A.Q.

Rt 1 Box 201 A

Hardeeville, SC 29927

**Phone:** (843) 247-9289

**Fax:**

**Email:** AIRQUALITY@HARGRAY.COM

**Your Results**

**Mold Analysis Report**

**NON-VIABLE Spore Trap M5**

**Report Number:** 012804-0188

**Received Date:** 1/28/2004

**Reported Date:** 1/28/2004

**Analysis By:** SSPTM, Inc.

*Alyssa Murray*

Alyssa Murray, QAQC

**Comments:**

<p>Penicillium/Aspergillus</p>	<p>THIS GROUP OF SPORES IS CONSIDERED COMMON TO INDOOR ENVIRONMENTS. COMMONLY FOUND IN SOIL, FOOD, CELLULOSE, AND ALSO CONSIDERED A COMMON CONTAMINANT OF FOOD. IT IS ALSO FOUND IN PAINT AND COMPOST PILES. IT MAY CAUSE HYPERSENSITIVITY PNEUMONITIS AND ALLERGIC ALVEOLITIS IN SUSCEPTIBLE INDIVIDUALS. IT IS REPORTED TO BE ALLERGENIC. COMMON CAUSE OF EXTRINSIC ASTHMA (IMMEDIATE-TYPE HYPERSENSITIVITY: TYPE I). ACUTE SYMPTOMS INCLUDE EDEMA AND BRONCHIOSPASMS; CHRONIC CASES MAY DEVELOP PULMONARY EMPHYSEMA. MANY SPECIES PRODUCE MYCOTOXINS, WHICH MAY BE ASSOCIATED WITH DISEASE IN HUMANS AND OTHER ANIMALS. TOXIC PRODUCTION IS DEPENDENT ON THE SPECIES OR A STRAIN WITHIN A SPECIES AN ON THE FOOD SOURCE FOR THE FUNGUS.</p>

The above information was compiled by PRO-LAB/SSPTM Inc. from the EPA "A Brief Guide to Mold, Moisture, and Your Home" and the NYC Dept of Health " Guidelines on Assessment and Remediation of Fungi in Indoor Environments", at the request of and for the exclusive use of the client named on this report. This document is not a legal mandate and should be used for informational purposes only. Currently there are no Federal regulations for evaluating potential health effects of fungal contamination and remediation. This information is subject to change as more information regarding fungal contaminants becomes available. For more information: visit <http://www.epa.gov/iaq/molds/index.html> or [www.nyc.gov/html/doh/html/ei/eimold.html](http://www.nyc.gov/html/doh/html/ei/eimold.html). This document was designed to follow currently known industry guidelines for the interpretation of microbial sampling, analysis, and remediation. Since interpretation of mold analysis reports is a scientific work in progress, it may as such be changed at any time without notice. The client is solely responsible for the use and interpretation of these recommended action guidelines. PRO-LAB/SSPTM Inc. makes no express or implied warranties as to such use or interpretation. PRO-LAB/SSPTM Inc. is not able to make and does not make a determination as to the environmental soundness, safety or health of a property from only the samples sent to their laboratory for analysis. The Client is hereby notified that due to the subjective nature of fungal analysis and the mold growth process, laboratory samples can and do change over time relative to the originally sampled material. PRO-LAB/SSPTM Inc. reserves the right to properly dispose of all samples after the testing of such samples are sufficiently completed or after a 7 day period, whichever period is greater. PRO-LAB / SSPTM, Inc. participates in the AIHA EMPAT program. Lab ID #163230

**PRO-LAB/SSPTM INC.**  
3300 Corporate Avenue, Bldg., 112  
Weston, Florida 33331  
Toll Free: 800-427-0550

**Test Address:**  
BELL- HHI SC, ,

**Client:**  
I.A.Q.  
Rt 1 Box 201 A  
Hardeeville, SC 29927

## Mold Analysis Report NON-VIABLE Spore Trap M5

**Report Number:** 012804-0188  
**Received Date:** 1/28/2004  
**Reported Date:** 1/28/2004  
**Analysis By:** SSPTM, Inc.

*Alyssa Murray*

Alyssa Murray, QAQC

**Comments:**

**Phone:** (843) 247-9289

**Fax:**

**Email:** AIRQUALITY@HARGRAY.COM

### Your Results

**Report Summary:** Pro-Lab Number: 012804-0188      Sample Submitted: Micro 5  
Unusual Mold Condition(s) Exists: Yes

**Unusual Mold Condition(s) Explanation:**

**If YES:** One or more of the samples in this report indicates the presence of elevated indoor mold spores or colonies for these specific locations only. Professional advice will be necessary to determine the appropriate actions to take to correct the conditions indicated. The information in your report and this summary may be used by an Industrial Hygienist or an Indoor Air Quality professional to assist in the determination of necessary actions.

**If NO:** The samples in this report do not indicate the presence of elevated indoor mold spores or colonies for these specific locations only

**If Inconclusive:** No comparison sample received.

For more information regarding mold cleanup or to find a Certified mold remediator in your area please call PRO-LAB at 800-427-0550

The mold identified in this report is often associated with excess moisture and can be a problem in indoor environments at high levels. Since mold requires water to grow, it is important to prevent moisture problems in buildings. The presence of mold, water damage, or musty odors should be addressed immediately. In all instances, any source(s) of water must be stopped and the extent of water damage determined. Mold can grow on virtually any organic substance, as long as moisture and oxygen are present. When excessive moisture accumulates in buildings or on building materials, mold growth will often occur, particularly if the moisture problem remains undiscovered or unaddressed. Building materials, such as drywall are made of cellulose and are highly absorbent, perfect surfaces for mold growth when wet. Moisture problems may include roof leaks, plumbing leaks, landscaping or gutters that direct water into or under the building, and unvented combustion appliances such as gas stoves. Water damaged building materials supporting mold growth should be cleaned or replaced as quickly as possible in order to ensure a healthy environment. Specific methods of assessing and remediating mold contamination should be based on the extent of visible contamination and the cause of the damage.

The above information was compiled by PRO-LAB/SSPTM Inc. from the EPA "A Brief Guide to Mold, Moisture, and Your Home" and the NYC Dept of Health " Guidelines on Assessment and Remediation of Fungi in Indoor Environments", at the request of and for the exclusive use of the client named on this report. This document is not a legal mandate and should be used for informational purposes only. Currently there are no Federal regulations for evaluating potential health effects of fungal contamination and remediation. This information is subject to change as more information regarding fungal contaminants becomes available. For more information: visit <http://www.epa.gov/iaq/molds/index.html> or [www.nyc.gov/html/doh/html/ei/eimold.html](http://www.nyc.gov/html/doh/html/ei/eimold.html). This document was designed to follow currently known industry guidelines for the interpretation of microbial sampling, analysis, and remediation. Since interpretation of mold analysis reports is a scientific work in progress, it may as such be changed at any time without notice. The client is solely responsible for the use and interpretation of these recommended action guidelines. PRO-LAB/SSPTM Inc. makes no express or implied warranties as to such use or interpretation. PRO-LAB/SSPTM Inc. is not able to make and does not make a determination as to the environmental soundness, safety or health of a property from only the samples sent to their laboratory for analysis. The Client is hereby notified that due to the subjective nature of fungal analysis and the mold growth process, laboratory samples can and do change over time relative to the originally sampled material. PRO-LAB/SSPTM Inc. reserves the right to properly dispose of all samples after the testing of such samples are sufficiently completed or after a 7 day period, whichever period is greater. PRO-LAB / SSPTM, Inc. participates in the AIHA EMPAT program. Lab ID #163230

**PRO-LAB/SSPTM INC.**  
3300 Corporate Avenue, Bldg., 112  
Weston, Florida 33331  
Toll Free: 800-427-0550

**Test Address:**  
BELL- HHI SC, ,

**Client:**  
I.A.Q.  
Rt 1 Box 201 A  
Hardeeville, SC 29927

**Phone:** (843) 247-9289

**Fax:**

**Email:** AIRQUALITY@HARGRAY.COM

## Mold Analysis Report NON-VIABLE Spore Trap M5

**Report Number:** 012804-0188  
**Received Date:** 1/28/2004  
**Reported Date:** 1/28/2004  
**Analysis By:** SSPTM, Inc.

*Alyssa Murray*

Alyssa Murray, QAQC

**Comments:**

### Your Results

**HEALTH EFFECTS:** Active mold growth in indoor environments may lead to adverse health effects. The presence of mold on building materials, as identified by the sampling results, does not necessitate that people will be exposed or exhibit health effects. In order for humans to be exposed indoors, fungal spores, fragments, or metabolites must be released into the air and inhaled, physically contacted (dermal exposure), or ingested. Whether or not symptoms develop in people exposed to mold depends on the nature of the fungal material (e.g., allergenic, toxic, or infectious), the amount of exposure, and the susceptibility of exposed persons. Susceptibility varies with the genetic predisposition (e.g., allergic reactions do not always occur in all individuals), age, state of health, and concurrent exposures. For these reasons, and because measurements of exposure are not standardized and biological markers of exposure to mold are largely unknown, it is not possible to determine "safe" or "unsafe" levels of exposure for people in general. The most common symptoms of mold exposure are runny nose, eye irritation, cough, congestion, and aggravation of asthma. Individuals with persistent health problems that appear to be related to mold or other types of air quality contaminant exposure should see their physicians for a referral to professionals who are trained in occupational/environmental medicine or related specialties and are knowledgeable about these types of exposures. Decisions about removing individuals from an affected area must be based on the results of such medical evaluation. Since mold is naturally present in outdoor environments and we share the same air between the indoors and the outdoors, it is impossible to eliminate all mold and their spores from the indoor environment.

The above information was compiled by PRO-LAB/SSPTM Inc. from the EPA "A Brief Guide to Mold, Moisture, and Your Home" and the NYC Dept of Health " Guidelines on Assessment and Remediation of Fungi in Indoor Environments", at the request of and for the exclusive use of the client named on this report. This document is not a legal mandate and should be used for informational purposes only. Currently there are no Federal regulations for evaluating potential health effects of fungal contamination and remediation. This information is subject to change as more information regarding fungal contaminants becomes available. For more information: visit <http://www.epa.gov/iaq/molds/index.html> or [www.nyc.gov/html/doh/html/ei/eimold.html](http://www.nyc.gov/html/doh/html/ei/eimold.html). This document was designed to follow currently known industry guidelines for the interpretation of microbial sampling, analysis, and remediation. Since interpretation of mold analysis reports is a scientific work in progress, it may as such be changed at any time without notice. The client is solely responsible for the use and interpretation of these recommended action guidelines. PRO-LAB/SSPTM Inc. makes no express or implied warranties as to such use or interpretation. PRO-LAB/SSPTM Inc. is not able to make and does not make a determination as to the environmental soundness, safety or health of a property from only the samples sent to their laboratory for analysis. The Client is hereby notified that due to the subjective nature of fungal analysis and the mold growth process, laboratory samples can and do change over time relative to the originally sampled material. PRO-LAB/SSPTM Inc. reserves the right to properly dispose of all samples after the testing of such samples are sufficiently completed or after a 7 day period, whichever period is greater. PRO-LAB / SSPTM, Inc. participates in the AIHA EMPAT program. Lab ID #163230